

4DAU74909

DDC FILE COPY

This document has been approved for public release and sale; its distribution is unlimited.

DOUGLAS AIRCRAFT COMPANY

79 10

11 021

CORPORATION

DISCLAIMER NOTICE

THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DDC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

MDC-J8213 Revision letter Contract number / F33700-78-C-0001

Copy number 26

Report number

12) 826

KC-10A CARGO SYSTEM MOCK-UP TEST,

11) 22 Aug 79

Revision date

Issue date AUG 2 2 1979

D. P. Danielsen Principal Engineer KC-10 Cargo Systems

Approved by

Director, Engineering KC-10 Program

OCT 12 1979)

Donald P. /Danielsen

This document has been approved for public reloces and sale; its distribution is unlimited.

DOUGLAS AIRCRAFT COMPANY

MCDONNELL DOUG

CORPORATION

116 400


FOREWORD

This report of a test performed on the KC-10A cargo system mock-up is submitted in accordance with Data Item number DI-T-3718/1 (Sequence No. A02D) under USAF contract number F33700-78-C-0001 for the KC-10 program. The test was conducted on June 18, 19 and 20, 1979, at Long Beach, Calif., by the Douglas Aircraft Co., McDonnell Douglas Corp., 3855 Lakewood Blvd., Long Beach, Calif. 90846.

Three USAF personnel witnessed the first 2 days of testing and two of them remained for the final 1/2 day. On June 18 and 19, the following were present:

Capt. Robt. I. Marx, ASD/YTT Flt Test MGr., KC-10 SMSgt. Willie J. Lorenz, AFALD/YT/MACSO Loadmaster SMSgt. Steve K. Johnson, AFTEC/TEZ Loadmaster

One June 20, Capt. Marx and Sgt. Lorenz were present.



ABSTRACT

A test was conducted on the KC-10A Cargo Handling System Mock-Up to evaluate the performance of the current design of the powered roller system.

The test consisted of running a total of 246 load/unload cycles with various Weights loaded on the pallets. Of these load/unload cycles, 135 were single HCU-6/E pallets and the remaining 111 were coupled HCU-6/E pallets (2 in train). These cycles simulate over 2 years of KC-10A palletized cargo operations.

The powered roller system functioned very well for the entire spectrum of loads. Single and coupled pallets were loaded laterally or rotated in the doorway easily. This test demonstrated that the system meets or exceeds its design requirements.

TABLE OF CONTENTS

		PAGE		
1.0 -	INTRODUCTION	1-1		
1.1	Test Objectives			
1.2	.2 Description Of Cargo Handling System Mock-Up			
1.3				
1.4	Cargo System Mock-Up Test Plan	1-3		
2.0	SINGLE PALLET OPERATION	2-1		
3.0	COUPLED PALLET OPERATION	3-1		
4.0	OPERATION WITH TWO POWERED ROLLERS ROTATED 900	4-1		
5.0	SUMMARY AND CONCLUSIONS			
APPENDIXES				
A	Figures and Photographs of Cargo Mock-Up Test	A-1		
В	Worksheets of Cargo Mock-Up Test	B-1		
C	KC-10A Pallet Study	C-1		

LIST OF ILLUSTRATIONS

FIGURE		PAGE
1 .	General Arrangement - KC-10A Cargo System Mock-up	A-2
2	Overview Looking Forward - Down	A-3
3	Overview Looking Left - Forward	A-4
4	Powered Roller	A-5
5	Pallet In Right Side Channel	A-6
6	Tread Cut On Powered Roller	A-7
7	Chipped Tread On Powered Roller	A-8
8	Pallet Cocked At End Of Loader	A-9
9	Pallet Partially Rotated	A-10
10	Chamfered End Ring On Powered Roller	A-11
11	Pallet Detend Against Jamb Protector Bracket	A-12
12	Pallets Coupled On 108-In. Side	A-13
13	Pallet Coupler	A-14
14	Bent Frame, Powered Roller	A-15
15	Coupled Pallets Rotated To Right Side Channel	A-16
16	Scuffed End Ring On Powered Roller	A-17
17	Rollers 1 And 4 After 236-Cycle Test	A-18
18	Rollers 2 And 5 After 236-Cycle Test	A-19
19	Rollers 3 And 6 After 236-Cycle Test	A-20
20	Rollers 7 And 8 After 236-Cycle Test	A-21
21	General Arrangement - KC-10A Cargo System Mock-up, Rollers 4 And 5 Rotated 90° Clockwise	A-22
22	Overview Of Doorway Area With Rollers 4 And 5 Rotated 900	A-23
23	Pallet Rotated To Left Side Channel	A-24
24	Pallet Rotation Unintended	A-25
25	Pallet Bottom Surface After Complete Test	A-26
26	Corner Area - Pallet Bottom Surface After Complete Test	A-27

1.0 INTRODUCTION

The main cabin cargo handling system consists (in-part) of a powered roller system, which provides lateral on-loading/offloading of cargo and capability for rotating over-length cargo through the cargo doorway.

Paragraph 1051BH of the Statement of Work (SOW), dated 30 September 1977, states that: "Tests shall be initiated on the cargo loading system mock-up to evaluate control system operation and system capability to rotate overlength loads and to move coupled pallets".

A cargo loading system mock-up was built as a development tool to demonstrate the ability of the powered rollers to move and rotate single and coupled pallets; the electrical circuitry of the system; and to develop operation techniques for training and cargo loading manual inputs.

Through the development phase, the cargo loading system mock-up was modified and changed to insure that the best combination of designs were evaluated.

1.1 TEST OBJECTIVE

The primary objective of this test was to evaluate the performance of the current design of the powered roller system. The test plan was derived using the Mission Profiles of Appendix II of the SOW to simulate real life conditions. The secondary objective of this test was to evaluate the effect of reorientation of two powered rollers as outlined in Review Item (RI) C101 submitted by USAF during the Furnishings and Equipment Critical Design Review (CDR) on 14 March 1979.

1.2 DESCRIPTION OF CARGO HANDLING SYSTEM MOCK-UP

The KC-10 Cargo System Mock-up used in this test/demonstration is shown in Figure 1 and by two overview photographs, Figures 2 and 3.

The mock-up consists of simulated loader and the KC-10A cargo handling system from fuselage stations 625 to 960 (approximately). Details of the mock-up include:

- 1) Loader Simulation

 To simulate the bed of a USAF 40K loader, cylindrical rollers were used adjacent to the aircraft door and the guide rails were spaced at 108.5 inches. The guide rails were flared open
- 2) Airplane Simulation

at the end as on the 40K loader.

- a) The cargo door sill conveyor assembly was simulated by a row of cylindrical rollers and an aft door jamb protector bracket (production part). These items were installed at the doorway area.
- b) Production omni-directional rollers were mounted on plywood simulating the KC-10A omni-directional conveyor assemblies.
- c) Eight powered rollers were installed in cutouts in the plywood. Locations are identical to the KC-10A system. The roller assemblies had prior usage during the development phase of the mock-up, but each roller shell had new tread on it for this test/demonstration. In Figure 4, the new tread can be seen as well as the aluminum alloy rings on the ends of the roller. The end rings are a production change which has been made to protect the tread from gouging by the latch detends on the edges of the HCU-6/E cargo pallets.
- d) The left-hand guide rail was positioned at X = +108.69, simulating the 27 pallet arrangement.
- e) The right-hand guide rail was positioned at X = -88.69. The guide rail has notches cut in it to simulate the individual segments of rails located in the omni-directional area of the KC-10A cargo handling system (Refer to Figure 3).
- f) A production type pendant control was used for this test/demonstration. The pendant is located at the forward edge of the simulated cargo door area.

1.3 DESCRIPTION OF TEST ARTICLES

Two HCU-6/E cargo pallets manufactured by the Brownline Division of Brooks and Perkins, Inc. were used for the test. "Flight test" weights were loaded on the HCU-6/E pallets to simulate the various weights of pallets.

A Douglas design pallet coupler was used to couple the HCU-6/E pallets together. This coupler is described in Paragraph 3.0 of this report.

1.4 CARGO SYSTEM MOCK-UP TEST PLAN

A test plan, based on the following, was developed to evaluate the performance of the powered roller system.

Mission profiles discussed in Appendix II of the SOW were used to determine the number and character of single and coupled pallet loads that would be carried aboard the KC-10A during its 20 year life span. This pallet study is found in Appendix C.

The equivelent of two years of service was considered sufficient to evaluate the powered roller system.

A total of 246 load/unload cycles were run, with pallets weight between 2000 and 10,000 pounds. A load cycle is defined as the movement of a pallet load from the "loader" into the "airplane" and back out to the "loader". The first 236 cycles simulated the 2 years of projected KC-10 service and the remaining 10 cycles were run with powered rollers numbers 4 and 5 rotated 90° clockwise to evaluate the effects this arrangement would have on pallet handling capabilities (Reference RI C101).

The following chart lists the sequence of events in the mock-up test/demonstration.

SEQUENCE OF ACTIVITY - CARGO SYSTEM MOCK-UP TEST						
TEST RUN	PALLET CONFIG.	PALLET LOAD 1000'S LB.	PALLET EXCURSION*	CYCLES**		
1	Single	5	To RS	45		
2	Single	10	To RS	5		
. 3	Single	5	To LS	45		
4	Single	10	To LS	5		
5	Single	5	Rotate To LS	20		
6	Single	10	Rotate To LS	5		
7	Coupled 108" Side	6/6	To RS	10		
8	Coupled 108" Side	2/2	To RS	75		
9	Coupled 108" Side	2/4	Rotate To LS	10		
10	Coupled 88" Side	2/4	Rotate To RS	10		
11	Coupled 108" Side	4/6	Rotate To LS	3		
12	Coupled 88" Side	4/6	Rotate To LS	3		
			SUBTOTAL 236			
	FOR RUNS 13-21, POWERED ROLLERS 4 & 5 WERE ROTATED 90° CLOCKWISE (REF. FIG'S. 21 & 22).					
13	Coupled 88" Side	4/4.2	Rotate To RS	1		
14	Coupled 108" Side	4/4.2	Rotate To LS	1		
15	Coupled 108" Side	4/4.2	To RS	1		
16	Single	5	To RS	1		
17	Single	5	To LS	2		
18	Sigle	5	Rotate To LS	1		
19	Single	5	To RS	1		
20	Single	10	To RS	1		
21	Single	10	Rotate To LS	1		
			TOTA	AL 246		

^{*} RS = Right side channel of pallets in airplane; LS = Left side.

^{**} One cycle is movement of pallet from loader into airplane and back out to loader.

2.0 SINGLE PALLET OPERATION

A total of 125 load cycles was run with single pallets having loads of 5000 or 10,000 lb., 100 cycles being straight lateral translations, simulating loading into a 25 pallet all-cargo configuration as shown in Figure 5, and 25 load cycles were rotated on entry and exit simulating loading the left-hand side of a 27 pallet all-cargo configuration.

After the first 10 cycles, a cut apporximately 0.6 in. long appeared on the tread of one roller (see Figure 6) but it did not increase during the remainder of the entire test.

Figure 7 shows a chip in the tread of roller No. 5 that was discovered after the first 48 cycles, the last 3 cycles at a 10,000-1b. load. Figure 8 shows that a pallet being offloaded may not be misaligned or it won't enter the loader's guide rails easily. In Figure 9, a pallet is in the process of rotation, and Figure 10, a chamfer on the end ring of a roller occured when the edge of a pallet was positioned on the edge of the roller. In Figure 11, a pallet was positioned so that one of its latch detents was against the door jamb protector bracket to determine if a hook-up would occur. The remedy for this condition is to pull the pallet away from the bracket by use of the powered rollers.

After 122 load cycles, it was noticed that roller No. 4 would not raise up when energized to drive toward the right side. The frame of the roller was bent (Figure 14) so that the erection mechanism was misaligned. The problem was corrected by replacing the frame. Simultaneously it was noticed that roller No's 4, 5 and 2 were missing one bolt each in the attachment pattern to their metal mounting plates, and at all 8 powered rollers many of the wood screws attaching the mounting plates to the wooden flooring were loose or missing. The omission of bolts and wood screws can be seen in Figure 4, 6, and 7 and is traceable to modifications made during prior development work

done on the mock-up. All missing attachments were installed, and no further difficulties were experienced with roller operations.

Basically, the powered roller system performed this portion of the test well in moving the single pallet laterally in the aircraft or rotating in the doorway area.

3.0 COUPLED PALLET OPERATION

A total of 111 load cycles was run with coupled pallets having total loads of 4000 to 12,000 lb. for the pair of pallets. The first 85 load cycles were straight lateral translations into the airplane, and the last 26 were rotated on entry and exit. The pallets that were rotated were coupled on either the 88 inch or 108 inch dimension.

Figure 12 shows coupled pallets being loaded and Figure 13 is a close-up of the pallet coupler. This coupler provides a 1-inch space between pallets as is standard in the KC-10A Cargo Handling System. Two couplers are required to couple two pallets. No loose parts or tools are required for attachment of the couplers. In Figure 15, a pair of coupled pallets has been rotated to the right side channel in the airplane.

In Figure 16, some scuffing on the end ring of roller No. 5 is seen, and the tread chip first shown in Figure 7 is enlarged to approximately 0.7 in. long, 0.5 in wide, and 0.15 deep at the deepest point. This was observed after 230 load cycles including 20 cycles rotating coupled pallets and 25 cycles rotating single pallets.

Figures 17, 18, 19, 20 are views of all the powered rollers, taken in pairs, showing the condition of the rollers at the completion of 236 load cycles.

The powered roller system performed this portion of the test very well. Lateral movement of coupled pallets was accomplished easily and the rotation was positive.

4.0 OPERATION WITH TWO POWERED ROLLERS ROTATED 90° (RI C101)

Powered roller No's 4 and 5 were rotated 90° clockwise to a longitudinal drive fixed position in order to evaluate the function of the roller system in this configuration, refer to RI Cl01 generated during the Furnishing and Equipment CDR. Figure 21 shows this arrangement and Figure 22 is an overview photo.

In general, this arrangement produced a considerable amount of unwanted pallet rotation, especially on single pallets moving toward the airplane door from the airplane's right side. A 5000-lb. pallet rotated approximately 30° on entry toward the right side and 75° on exit. A 10,000-lb. pallet rotated approximately 20° on entry, and on exit was rotated 45° by the time it got to the airplane centerline (similar to Figure 24). Since 86% of the anticipated pallet loads in KC-loA operations do not require rotation, the unwanted pallet rotation associated with this mixed arrangement is very undesireable. Rotating single or coupled pallets to the left side worked quite well except for final adjustments. Figure 23 shows a pallet position on the left side with no more alignment by powered rollers possible.

In this arrangement the operator must handle more complex switching operations in rotating pallets because he must handle power controls in 4 directions instread of 2.

Aft translation produced by rollers 4 and 5 was an assist, although it did tend to produce some rotation because the point at which power is applied is eccentric to the pallet.

5.0 SUMMARY AND CONCLUSIONS

The basic powered roller system design performed very well for the entire spectrum of loads. Lateral onloading/offloading of single and coupled pallets were accomplished easily and effectively. Rotation of single and coupled pallets was positive and easy to control. The operator's pendant control techniques were easily learned and applied. This test demonstrated that the powered roller system meets or exceeds its design requirements.

Wear, tear, or tread gouging on the powered rollers was not sufficient to be considered disabling damage. All rollers were functioning normally at the completion of testing. The bent frame on roller No. 4 (causing a 50% loss of function) was traceable to loose attachment of the rollers to the mock-up flooring.

Roller tread wear was negligible, measuring .000 to .020 in. on the radius, considering that the testing simulated 2 years of KC-10A palletized cargo operation.

In addition, this test demonstrated that rotating two rollers 90° , as indicated in RI ClO1, created unwanted pallet rotation when moving pallets in/out of the aircraft and complicated the operator's control procedures.

During the development phase concern was expressed about the wear on the bottom surface of the HCU-6/E pallets when rotating through the cargo door. Upon the completion of this test, photographs were taken of the bottom surface of one of the pallets and a close-up of one corner, see Figures 25 and 26. The photographs show that there are numerous marks and small indentations over the bottom surface, but no serious damage. The other pallet used in the test looked the same.

These HCU-6/E pallets have been at the Long Beach facility for approximately eight years. They were first used on the DC-8 Power Pack Shuttle mock-up, through the development phase of the KC-10A mock-up.

MCDONNELL DOUGLAS CORPORATION


and then for the 2-year simulated KC-10A palletized cargo operation.

There is one area that should be noted. During this test a sharp edge was found on the lower corner of the pallet latch detents, as seen in Figure 13. This edge condition may have been produced by displacing and cold working the material during pallet movements on various mock-up operations, and may be the cause of roller tread damage and end ring wear that occured during the early testing.


APPENDIX A
FIGURES AND PHOTOGRAPHS
OF CARGO MOCK-UP TEST


CONTROL STATION


108.





GENERAL ARRANGEMENT —
CARGO SYS. MOCK-UP
KC-IOA


























































CONTROL STATION



GENERAL ARRANGEMENT —
CARGO SYS. MOCK-UP
KC-IOA


ROLLERS 4 AND 5 ROTATED 90° CW














APPENDIX B
WORKSHEETS OF CARGO
MOCK-UP TEST

JUNE 18, '79): 1052 PALLET TALLET TEST CYCLES LOAD, LE. CONFIG. RUN LATERAL TRACKING SOMETIMES DRIFTS RS SINGLE 45 5000 AT 10 CYCLES, PHOTO \$ 2 ROLLER CECRUB MAR SINGLE 10,000 PHOTO # 5 POLLER 5 2 R. I AT 3 CYC AT 11 CYC, 14070 = 45 SINGLE 1.5 5000 5 41.5 10000 5 ROTATES PHOTO - PALLET PARTIALLY ROTATED SINGLE 20 5c00 2ND CYCLE: #4 ROLLER PUSHED OFF OF CAM. #4 AND # 2 HAD ONE INSTL 6 ROTATED 10000 BOLT MISSING. ALL COLLERS WERE MISSING WOOD SCREWS ATTACHING MOUNTING PLATE TO PLYWOOD,
4 HAD PENT FRAME, WOULD NOT ERECT WHEN DRIVEN TO R.S. FRAME FEPLACED. bocoloce CruPLED COUPLED ON 108" R.S. 10 EDGE. NO ROTATION. VERY LITTLE MANUAL ASSIST GOOD TRACKING. 19. 79): JUNE 2000 2000 11 75 Crupled 8.5 AFTER 24 CYC, PHOTO PAIRS OF ROLLERS AT COMPLETION, NO CHANGE IN CONDITION OF ROLLERS. 2000 COUPLED ON 108" EDGE; ROTATE TO L. S. L. S. 10 9 ROTATED COUPLED COUPLED ON SEPELCE, KOTATE TO R.H. 2000 10 ROTATED COUPLED 10 1000 APPROX TO X 76 , SE SEEP AT DEEPEST POIL COUPLED ON 108" SIDE, ROTATE TO L.S. 11 POTATED COUPLED 4000/6000 3 COUPLED ON 88" SIDE; ROTATE TO L.S. 12 ROTATED COUPLED 4000/6000 3 PHOTO 8 ROLLERS, ZROLLERS PER PHOTO.
ROTATED POLLERS 4 \$ 5; TAKE O'ALL PHETOS.

= 4 2 OF 2

Ker	LERS 4	\$ 5 KC7	ATED 90	o cue		H 2 OF	2
TEST	FALLET	PALLET	CYCLES				
- RUN	CONFIG.	LCAS, LB	Cicces				
12 RS.	COUPLED	4200	1	REQUIRED	CONSILER TAS WORL	IDE; ROTAT	E TO R.S
				ASSIST. N	RRANGE'T	TABLE AS	PRIGINAL
14 2.5.	CourlED	4000	1	COUPLE A C	N 108" EID ME DEGRE LER LAYOU	E ; ROTATE	Te L. S
1. KLINIC				CRIC'L ROL	ER LAYOU	7, EXCEPT	THAT
				POSGATOR	CHING DE	C WAS CO	DOED -
ICD =	0.112150	4000		COUPLED 10	ERENTIAL B" SIDE.	GOUGES,	NO ROTAT
15 R.S	COUPLED	4200	1	PATATEL F	B" SIDE. OM AIRPLAI U'C. NEED!	P MANUA	ND CE.ALI
17				LON DOORW	la P		
16 R.S	SINGLE	5000		GOING IN,	NINTENDED 75° ON E	KIT, MANU	N ASSIST
17 L. E.	•	5000	2	ROTATION	NINTENCE ON EXIT		
18 ROTATE	11	5000	1	INADEGU	TATION, B		
19 R.S.	н	5000	1	AFTOTRA	NSLATICH S SLOW (PATION CO	13 4.
20 R. E	11	10,000	1	STRAIGHT BEFORE	IN, 207	ROTATED CONTACT	roo cw
					TION ON E	IT AT TIM	PHOTO
ZI ROTATE	SINGLE	10,000	1	GOOD ROTA	TICH BUT	INADEGUA	7 E.
- Refrie			,	CONTROL	. 790 7.00	OKIC TIT	PH070
	PHOTO ROL	LERS 1	THRU 6				
		• • •	1-246c	10150			
		7074	Larc	40002			
				TREAD WE	AR WAS	MEASURED	ON
				TO BE	AR WAS / ROLLERS WITHIN	OCO AND .	ND IN
				, , , , ,		OU PINE .	- M.

APPENDIX C
KC-10A PALLET STUDY

KC-10A PALLET STUDY

1.0 PROBLEM

Determine a spectrum of pallet loads single and coupled, that are likely to be carried aboard the KC-10A during it's 20 year life span. These data will be utilized for the testing of the Cargo Loading Modkup. The objective is to simulate representative cargo operations on the Cargo Loading Mockup to evaluate wear on the powered rollers.

2.0 STUDY APPROACH

The primary mission of the KC-10A is as a tanker aircraft. The accommodation for cargo is considered secondary but an important role.

To determine the number and character of single and coupled pallet loads carried during the KC-10A life time, the following must be known:

- 1. Type of cargo mission to be flown.
- Number of cargo missions by type of mission over the 20 year life span.
- 3. Type of cargo carried on these missions.
- 4. Determine from the type of cargo the number of single and coupled pallets required for airlift.
- Determine the approximate weight of these single and coupled pallets.

3.0 STUDY APPROACH AND ASSUMPTIONS

The following assumptions were used in this study:

3.1 TYPE OF CARGO MISSIONS

The only information available for the type of mission the KC-10A will be flying is defined by the mission profiles described in the Statement of Work Appendix II. Although it has been recommended that these mission profiles be only used for Life-Cycle costs, the objectives of this study

are to determine the wearability of the powered rollers. Therefore, these mission profiles are applicable for this study. Attachment I of this study contains these KC-10A mission profiles.

Three of the ten mission profiles are defined as cargo carrying mission: Mission number 2-TAF DEPLOYMENT/REDEPLOYMENT with 33,756 pounds ACL (allowable cabin load) available, Mission number 3-CARGO TRAINING with 76,000 pounds ACL available, and Mission number 5-CONTINGENCY CARGO with 171,508 pounds of ACL available.

3.2 NUMBER OF CARGO MISSIONS

USAF letter number YT(78-1-8) dated 1 March 1978 indicated that the ATCA annual basic utilization rate was 540 hours per aircraft with the potential surges and contingencies raising the rate to 1200 hours per year per aircraft. This letter is attached as Attachment 2 of this study.

The 540 hour utilization rate is assummed to be peace time and the 1200 hour rate as surge (wartime) rate.

The following assumption is made - During the 20 year time span the KC-10A will fly 5 years at the surge rate (1200 hr/year) and 15 years at the peace-time rate (540 hr/year).

Table 1 was derived to show the total number of missions by profile over the 20 years.

Results indicate that 213 missions (flights) for profile No. 2 would be flown during the 20 years. This was derived as follows:

Peace time -

81 flights/year X 10% flights are profile #2 X 15 years = 122 flights
Surge —

131 flights/year X 10% flights are profile #2 X 5 years = 91 flights
Total flights = 122 + 91 = 213

MDC JR213

TABLE I ATCA MISSION PROFILES

			1							-
	MISSION	MISSION PROFILE	FLIGHT TIME (HOURS)	GROUND TIME (HOURS)	PERCENT	PERCENT CARGO MISSIONS FLOWN ACL AVAILABLE	TOTAL PEACE- TIME MISSIONS FOR 15 YEARS	TOTAL SURGE MISSIONS FOR 5 YEARS	TOTAL MISSIONS FOR 20 YEARS	
	ı	TAF EMPLOYMENT	7.10	.58	2	•	24	18	42	
	2	TAF DEPLOYMENT/REDEPLOYMENT	7.33	.58	01	33,756 lb	122	16	213	
	8	CARGO TRAINING	4.73	.58	-	76,000 lb	12	6	12	
	4	MAC LONG HAUL AND/OR TRAINING	5.5	.58	30		366	272	863	
	2	CONTINGENCY CARGO	11.62	.58	1	171,508 16	12	6	12	_
C-4	9	B-52 TRAINING	5.80	95.	9	•	73	54	121	
	7	B-52 CONTINGENCY (TWO B-52S)	6.82	.58	1		12	6	12	
	8	FIGHTER TRAINING (LOW ALT. 160-220)	2.97	.58	-		12	6	12	
	6	FIGHTER TRAINING (MED. ALT, 260-310)	26.9	.58	40	•	488	362	850	
	10	FIGHTER TRAINING (MED ALT 260-310) & KC-10A REFUELING TRAINING	8.50	.58	8	•	86	72	170	
	TOTAL	TOTALS PER 100 FLIGHTS	£99	58	100					
	YEAR PER YI	YEAR TOTALS BASED ON 540 FLIGHT HOURS PER YEAR	540	47	81.4					
	YEAR	YEAR TOTALS BASED ON 1200 FLIGHT HOURS PER YEAR	1200	105	181					170 01
				TOTAL 20 YEA	TOTAL NUMBER OF 20 YEARS	JF FLIGHTS OVER	1219	905	2124	1213

Using the same formula for profiles No. 3 and 5, except using 1%, results in a total of 21 flights each.

3.3 TYPE OF CARGO CARRIED BY MISSION PROFILE

Mission profile Number 2 is defined as a TAF (Tactical Air Force) Deployment/Redeployment. This mission envolves the deployment of a fighter/interceptor squadron including the squadron's support equipment. The KC-10A will refuel aircraft as well as carry cargo. The available ACL is 33,756 pounds. The F-15 squadron has been selected for this mission profile.

Mission profile Number 3 is defined as a Cargo Training mission. This mission is assumed to be a normal channel cargo operation transporting palletized cargo from one Air Force base to another. The palletized cargo includes single and coupled pallets. Available ACL is 76,000 pounds.

Mission profile number 5 is defined as a contingency cargo mission. This mission is assumed to be an emergency cargo mission, such as the resupply of ammunition. Available ACL is 171,508 pounds.

- 3.4 DETERMINE PALLET REQUIREMENTS FOR THE THREE CARGO MISSION PROFILES
 This section determines the number of pallets that will be loaded aboard
 the KC-10A for each type of mission profile during the 20 years.
- 3.4.1 TAF Deployment/Redeployment Mission Profile

The F-15 squadron's support equipment consist of 198 single items weighing 573,367 lbs. Attachment 3 contains the list of these 198 items sorted by NSN (National Stock Number).

An assumption was made that all equipment would be pre-loaded on 463L pallets before loading into the KC-10A.

Each item on the list was reviewed to determine if a single or double

pallet was required for loading. When possible small items were grouned together on a single pallet. However, a complete study to utilize all of the stacking surface on the pallet was not done. The 198 items results in requiring 94 single pallets and 84 coupled pallets.

A number of items which are loaded on coupled pallets are too long for loading across the aircraft and must be rotated through the cargo door. Figure 1 shows the maximum length of cargo, versus height, that can be loaded without rotation. This figure represents the maximum contours for 463L pallets in the KC-10A. The six inch clearance rule was used to determine if rotation was required.

Table II lists the 18 items which must be rotated through the cargo door. The first 5 items in the table are towbars, which are very long, but weigh only 415 pounds each. These items can be loaded manually rather than using the powered roller systems.

For the F15 squadron the total pallet requirements are:

94 - SINGLE PALLETS

84 - COUPLED PALLETS:

66 - NO ROTATION REQUIRED

13 - ROTATION REQUIRED

5 - MANUAL ROTATION

These single and coupled pallets represent 262 pallet nosition for loading in the KC-10A $(94 + (84 \times 2) = 262)$.

The configuration of the KC-10A during a TAF deployment/redeployment will either be the 23 pallet/20 passenger mixed configuration or the 27 pallet all cargo configuration. The total number of KC-10A's required to carry the 262 pallet positions are:

23 Pallet System:

$$\frac{262}{23}$$
 = 11.4 or 12 KC-10's

FIGURE I

MDC J8213

AMERICA MAXIMUM LENGTH OF CARGO LOADABLE WITHOUT ROTATION (INCHES)




TABLE II - F15 SOUADRON

ITEMS WHICH REQUIRE ROTATION THROUGH THE CARGO DOOR

no.	NSN	HOMEHICLATURE	L	М	Н	MT
5009	1730-00-640-8020	TOWBAR A/C	296	57	30	415
5031	1730-00-640-8080	TOMPAR A/C	296	57	30	415
5032	1730-00-640-8080	TOUBAR A/C	296	57	30	415
T016	1730-00-640-8080	TOWBAR A/C	296	57	30	415
T197	1730-00-640-8080	TOUBAR A/C	296	57	30	415
E301	1740-00-713-5903	TRL 3000 1/F15 ENG	216	60	39	4360
T026	1740-00-713-5908	TRL 3000 11/F15 ENG	216	60	50	4360
T027	1740-00-713-5908	TRL 3000 H/F15 ENG	216	60	89	4360
T028	1740-00-713-5908	TRL 3000 W/F15 ENG	216	60	85	4360
T029	1740-00-713-5908	TRL 3000 W/F15 ENG	216	60	89	4360
T030	1740-00-713-5903	TRL 3000 11/F15 ENG	216	60	85	4360
T303	1740-00-713-5908	TRL 3000 1/0 ENG	152	58	80	1360
T019	1740-00-713-5908	TRL 3000 11/0 ENG	152	58	89	1360
5043	2330-L0-021-3648	TANK DOLLY	228	88	47	863
5044	2330-L0-021-3648	TANK DOLLY	228	88	47	863
T214	4920-00-438-3812	M37 THRUST TRL	201	64	85	5490
T215	4920-00-438-3812	M37 FUEL TK TLR	192	97	96	5360
T184	3990-00-820-9890	463L PALLET TRAIN	176	108	84	9910

DIMENSIONS IN INCHES AND WEIGHT IN POUNDS

$$\frac{262}{27}$$
 = 9.7 or 10 KC-10's

However, the limiting factor for carring the TAF support equipment is ACL,

To determine the average number of pallets per KC-10, divide the total number of pallets type by the total number of KC-10's required to carry the equipment.

$$\frac{94}{17}$$
 = 5.53 Pallets/KC-10

Coupled Pallets (no rotation required)

$$\frac{66}{17}$$
 = 3.88 Pallets/KC-10

Coupled Pallets (rotation required)

$$\frac{13}{17}$$
 = 0.76 Pallets/KC-10

Coupled Pallets (manual rotation)

$$\frac{5}{17}$$
 = 0.29 Pallets/KC-10

To determine the total number of pallets by loading configuration that will be loaded during the 20 year life span, multiply the pallets by the total number of sorties each KC-10 will experience during the 20 years. The total number of sortie/KC-10 is 213 for the 20 years.

This results in the following:

TAF DEPLOYMENT/REDEPLOYMENT MISSION PROFILE

Total number of single pallets = 213 X 5.53 = 1178

Total number of coupled pallets

 $(no rotation) = 213 \times 3.88 = 826$

Total number of coupled pallets

(rotation required) = $213 \times 0.76 = 162$

Total number of coupled pallets

 $(manual rotation) = 213 \times 0.29 = 62$

3.4.2 Cargo Training Mission Profile

This mission involves the accommodation of 463L pallets in a normal cargo operation. The preloaded 463L pallets assigned to the nine types of fighter/interceptor squadrons were used to represent the 463L pallet world.

These are 442 pallets listed in the nine squadrons, 18 of these pallets are coupled pallets or 4% of the total.

The configuration of the KC-10A for a cargo training mission is assumed to be the 23 pallet system (delivery configuration).

The total number of coupled pallets per aircraft is 4% of 23 pallets or 0.92 coupled pallets/KC-10. The total number of single pallets is $23 \times 96\% = 21.08 \text{ pallets/KC-10}$.

The KC-10 will fly 21 cargo training missions during its 20 year life span. Therefore the total number of pallets loaded will be:

Coupled Pallets:

21 X 0.92 = 19 pallets/KC-10A

Single Pallets:

21 X 21.08 = 444 pallets/KC-10A

3.4.3 Contingency Cargo Mission Profile

This mission involves the carring of ammunition loaded on single 463L

MCDONNELL DOUGLAS CORPORATION

pallets.

The KC-10A pallet configuration will be the 27 pallet all cargo configuration where 11 pallets must be rotated 90 degrees for loading on the left side of the aircraft and 16 pallets require no rotation.

Total number of pallets loaded in the 21 KC-10's during the 20 years are:

Single Pallets (rotation require!):
21 X 11 = 231 pallets/KC-10A

Single Pallets (no rotation):
21 X 16 = 336 pallets/KC-10A

3.4.4 Determine Approximate Weight of Pallets


SINGLE PALLETS (NO ROTATION)

Figure 2 show a distribution of 463L pallet net weight from a previous Douglas study. The pallet weights range from 300 pounds to 9700 nounds with the average net weights at 4661 pounds. When adding the tare weight of 354 pounds (nets and pallet) to these values, the average weight is 5,015 pounds and the minimum weight 6.54 pounds and 10,054 pounds maximum weight. The weight distribution between 1000 and 8500 pounds is fairly uniform.

For test purposes for the cargo loading mockup, the weights selected for a single pallet are 90% at 5,000 pounds and 10% at 10,000 pounds. These values represent higher weights in comparison to distribution represented in Figure 2, but simplify testing setup. These values will be used for single pallets where no rotation is required.

SINGLE PALLETS (ROTATION REQUIRED)

The single pallets selected are loaded with ammunition. Douglas conducted a CRAD study in 1975 which investigated Army ammunition resupply characteristics. From this study, it was estimated that 25% of the pallets would weigh approximately 10,000 pounds and the remaining 75%,5000 pounds.



COUPLED PALLETS (NO ROTATION)

Coupled pallets are used to accommodate wheeled vehicles and equipment. Reviewing the weights of the items, which are not rotated, the weights for 10% of the pallets is 12,000 pounds (6000 pounds per pallet) and 4000 pounds (2000 pounds per pallet) for the remaining 90%.

COUPLED PALLETS (ROTATION REQUIRED)

Coupled pallets which require rotation consist primarily of aircraft engines on transportation trailers. The weight of these items are not evenly distributed on the coupled pallets. The weights have been estimated to be 6000 pounds (4000/2000 pounds) for 80% of the pallets and 10,000 pounds (6000/4000 pounds) for 20% of the pallets. These weights apply for coupling on the 88 or 108 inch dimension of the pallet.

3.5 SUMMARY OF PALLET LOADING REQUIREMENT FOR THE KC-10A DURING 20 YEARS Table III list the summary of pallet loadings for the three mission profiles over a 20 year time span for each KC-10A. Included are the estimated weights for the pallets.

TABLE III SUMMARY - PALLET STUDY

TOTAL NUMBER OF PALLET LOADING OVER A 20 YEAR SPAN (ASSIMED 5 YEARS AT THE SURGE RATE OF 1200 FLIGHT HOURS/YEAR AND 15 YEARS AT THE PEACE TIME RATE OF 540 FLIGHT HOURS/YEAR)

	MISSION #2 TAF DEPLOYMENT/ REDEPLOYMENT*	MISSION #3 CARGO TRAIHING	MISSION #5 COMTINGENCY CARGO	TOTAL
SINGLE PALLETS HO ROTATION REQUIRED 90% @ 5000 LB., 10% @ 10,000 LB.	1178	444	336	<i>5</i> 961
SIMPLE PALLETS POTATION REDUINED 75% @ 5000 LB., 25% @ 10,000 LB.			231	231
COUPLED PALLETS 108 INCH DIMENSION NO ROTATION REQUIRED 90% @ 4000 LB. (2K/2K), 10% @ 12,000 LB. (6K/6K)	826	61	•	845
COUPLED PALLETS ROTATION REQUIRED				791
80% 6 000 LB. (2K/4K), 20% 6 10,000 LB. (4K/6K)	81	•	•	
80% @ 6000 LB. (2K/4K), 20% @ 10,000 LB. (4K/6K)	81	•	•	
COUPLED PALLETS MANIJAL ROTATION (415 LB. TOWBAR)	62	-	-	29

ASSUMES TAF DEPLOYMENT EQUIPMENT IS PREPALLETIZED AND NOT LOADED ON A PALLET SUBFLOOR.

TO:

C. W. Andrews, C1-251

FROM:

R. D. Dangaran, C1-253

SUBJECT: KC-10A MISSION PROFILES

COPIES:

K. Akamatsu, Avionics G. W. Johnson, Maintainability R. E. McConnelly, ARB F. G. Appleby, Project W. L. Miles, Human Factors K. M. Carpenter, Electrical R. L. Clepper, Structures O. J. Minnich, Interiors D. L. Gibler, Project J. A. Riccobono, Mechanical J. J. Heffernan, Acoustics G. A. Schlanert, Project R. W. Howard, Environmental H. F. Winchester, Power Plant

Attached is a copy of the ten basic KC-10A mission profiles described in the Statement of Work Appendix II. The revised mission profile number 9R and the modified mission profile number 9A are also included. Mission profile number .9A describes the hose and reel refueling method to be used in the reliability allocations, assessments and analysis report.

These profiles describe operational characteristics that can be used in establishing design criteria and reliability analysis requirements. Timing of some events and the amount of time required to checkout and/or stow the refueling equipment were estimated based on the best available information at the time.


Comments and/or corrections to these profiles are solicited.

R. U. Abrace R. D. Dangaran KC-10A Reliability & Safety


yd

attach.

			1	-	1	1	1	1	-		-						T	i
MISSION NEWSER	MISSICH PROFILE	FLIGHT TIME (AGURS)	GROUND TINE	PERCENT FLOJIN	8 GO LANDINGS	HOOKUPS HO. OF BOOM	HOOKUPS HOOKUPS	HOOKUPS HO. OF HOSE	FUEL OFFLOAD (POURIDS)	FUEL ONICOAD (POURIDS)	DEPLOYMENTS (CYCLES) (CYCLES)	NO. OF HOSE (CYCLES)	FUEL TRÀISFER ONLOADING TIME (HOURS)	FUEL TRANSFER OFFLOADING TIME (HOURS)	*SOON COMPUTER OPERATING TINE - (SAUNH)	600M FLT. CONT. 0=EPATING TIPE (HOURS)	DPEPATING TIME OPERATING TIME (HOMES)	STRUTURAL INTERFACE TIME (HCU'S)
-	TAC EMPLOYMENT	7.10	.58	2	0	12	0	0	61,000	•	3	,	0	.75	5.60	1.33	5.18	5.35
2	TAC DEPLOYMENT/ REDEPLOYMENT	7.33	. 58	91	0	8	0	0	150,000	0	۵	0	0	1.43	6.32	2.18	8.90	6.07
-	CARGO TRAINING	4.73	.58	-	0	0	0	0	0	•	•		0	0	0	0	0	0
•	MAC LONG HAUL AND/OR TRAINING	5.50	.58	8	w	т	0	0	000*56	0	-	0	0	.47	29.2	.83	2.20	2.37
s	CONTINGENCY CARGO	11.62	95.	-	0	0	-	ė	•	136,418	0	0	.28	0	0	0	0	0
•	B-52 TRAINING	5.80	.58	9	6	12	0	9	50,000	0	2		0	1.50	4.10	2.00	3.68	3.85
•	B-52 CONTINGENCY THO B-52s	6.82	95*	-	0	2	0	9	140,000	0	-	0	0	1.08	4.12	1.50	3.70	3.87
80	FICHTER TRAINING (LCM ALTITUDE 160-220)	5.97	.58	-	8	25	0	e	90,000	0	2	0	0	1.50	4.20	2.00	3.78	3.95
•	FIGHTER TRAINING (HED. ALTITUDE 260-310)	6.97	85.	Q .	s .	\$	0	0	160,000	0	2	0	0	2.00	4.75	2.50	4.33	4.50
2	FIGHTER TRAINING (HED ALTITUDE 260-310) 2 KC-10A REFUELING TRAINING	8.50	.58	8	s	84	و	0	160,000	000*00	2	0	37.	2.00	4.73	2.50	۸.٦2	4.48
10	TOTALS PER 100 FLIGHTS	693	28	100	411	2716	49	0	12652 K	776,418	197	0	6.28	137	414	136	120	189
55	YEAR TUTALS BASED ON 540 FLIGHT HOURS PER YEAR	540	47 .	18	335	2212	40	0	10305 K	632,377	160	0	11.3	112	337	152	192	317
						RELIABILITY	ILIT'	100000	MOTFIED MISSIONS	ONS								
g	FIGHTER TRAINING (BOOM)	6.97	.58	38.8	9	48	0	0	160,000.	•	2	•	•	2.00	4.75	2.50	4.33	4.50
8	FIGHTER TRAINING (HOSE)	6.97	89.	1.2	9	•	0	\$	120,000 (EST,)		0	2	0	2.00	•		0	4.50
•	INCLUDES 15 MINUTES GROUND CHECKOUT TIN	SHECKOUT	TIVE													İ		A




MISSION PROFILE NUMBER 1
TAC EMPLOYMENT



2 PRCFILE NUMBER MISSION


TAC DEPLOYMENT / P.E. DEPLOYMENT




MISSION PROFILE NUMBER 3

TRAINING

C-19



MAC LONG HAUL AND / OF TRAINING




MISSION PROFILE NUMBER

V


CARGO

CONTINGENCY




MISSION PROFILE NUMBER 6


B-52 THAINING




MISSION PROFILE NUMBER 7
B-52 CONTINGENCY (TWO B-52 15)




FIGHTER TRAINING (LOW ACTITUDE 160-220)



FIGHTER TRAINING (MED ALTITUDE 260-310)



FIGHTER TRAINING (MED ALTITUDE 240-310)



FIGHTER TRAINING & KC-10A REFUELING TRAINING (MED ALTITIADE 260-310)

DEPARTMENT OF THE AIR FORCE MEADQUARTERS AIR FORCE ACQUISITION LOGISTICS DIVISION (AFLC) WRIGHT-PATTERSON AIR FORCE BASE. OHIO 45433

YT (78-1-8)

CORRESPONDENCE

CONTROL C1-304

ATCA Utilization Rate RECORDED TO

-11 :: A.

End. 1 8 71A2 78 from: flavel Flant Rep. Office To Douglas Aircraft Co., Long Beach, Calls. For: Action indicated

Information

! Action

Regiy Prior To

1 MAR 1978

By direction

NAVPRO

Douglas Aircraft Company Attn: Mr. G. D. Staffieri Mail Station C1-241 (35-33) 3855 Lakewood Boulevard Long Beach, California 90846

IN TURY

- 1. Per your request at the ATCA system review, 8 February 1978, the following information is provided.
- 2. Current Air Force planning is for an annual basic utilization rate of 540 hours per aircraft, plus surges and contingencies which may raise this rate to 1200 hours per year. Mission distribution shall be as specified in the statement of work, Appendiculation and the statement of work, Appendiculation shall be as specified in the statement of work, appendiculation shall be as specified in the statement of work, appendiculations and the statement of work, appendiculations are specified in the statement of work, appendiculations are supplied to the statement of work, appendiculation are supplied to the statement of work, appendiculation are supplied to the statement of work, appendiculation are supplied to the statement of work are supplied to the supplied to the statement of work are supplied to the supplied to th dix II. This planned utilization rate, however, shall not effect the specification requirement for a boom with a structural life of at least 30,000 hours (Ref ATCA Specification, Paragraph 03-80.01.00).

TECHAS E. BLHAN Dop Prgs Mgr for Business Dep for Advanced Tanker/Cargo Aircraft



COPRESPONDED		-	
	18027 Ket!	Pani Cawl	l:fe
gulluder -4	1		1
hadai 3 mare		7	
Fregista G. e	- -		1-1
41/1m24		-	-!
Contracts V	-		مرا
:			1
haity 8. : a.	!	7	
my Con and		-	-:
Tenna!		-	
3.7			-
		1	- :

01006

sustants da, 417

= COUPLED PALLET S = SINGLE PALLET

SCALMADUATAN SEDAURUN TYPE (MINUR) ** LEUAURUN EUGLPMENT LEULINGONDUT 2/5 TALES TO THE PARTY OF THE PARTY 4 0 f 3 A 14 0 f 4 f 8 f 4 m A 4 3 m A 4 3 f 4 5 f 4 f A 5 f A 6 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f A 7 f

をあるられらららららららららららららららっとのアンスタング Kind Control C

NSALTALGELIAND SAUADAUR TYPE (AIRORIT* TOTALS 350 PICETACES POLICE AT CHATORECUL ARCHARACA AREA COTAL MERICE PROPER PROCESS OF A CHARACA ARCHARACA
ander Sauschus Egulenent Listz. Rough

		-30.5 -30.5	400	200	000	229	30.7	33	23	107	102	30	200	000	(A)	000	200	59	30	22	20	44	200	4	24	33.	33	
		1000	000	200	၁၁୯	20	100	00	00	00	20	3.3	00	0:	3.3.	7	027	5,	22	20	65	0.7	70	50	30	1.1	224	
		7 2008	176	0.00	00 00	00 ±	္ ထို အထိ	300	883	38	38 88	8 3 8 3	3.0	(C)	3.00 3.03	1001	000	000	100	33	Ca	23	200	300	200	000	200	
		184.24 195.24 195.24	243	140	48. 48. 50.7	100	42	445 500 500	288 200 200 200 200 200 200 200 200 200	262	252	528 387	415	3	14	273	27.2	51.7	1000	122	150	171	121	121	121	121	121	
	**(YON1	ME1GH1 3178 4556 4462	2362	17.0	3250	21.12	7007	4310	7927	4467	7985	4774	1740	2579	6025	1330	1330	0000	1330	00001	1750	100	193	1.98	793 743	99	11.8	L= 162,306
	TYPE (MINGK) *		TRAIN(2)																									Sub total:
NUV	LUADEDA	¥																									1374 1374	
LISTING.NUV7	1	TENCIALLE	400	111	1 4	1 3/1	1	וונו	בנו	TI II	ניננ	11	41	ini.	1	ניני		o car			-	Lat	23	30	30	300	35	
1		2277	44	4	444		33	14	44	Y S	त्र	444	44	PAL	1. A. P.	14	3011	3	334	1001	ALE	E SECTION	1227	150	250	110	2 4	
	UNA I MUD	5 3 3 3	41	4 4	200	1 4 4	3.5	44	50	3 5	20	1.1	1 1	4	1.4	20	2		3	1	F	33	3	5	30	3	I Č	
THEWATOR	והאו	5 3 3 3	41	4 4	200	1 4 4	3.5	44	50	3 5	20	1.1	1 1	4	1.4	20	2		3	1	F	33	3	5	30	3	I Č	
EQUIPMENT	והאו	5 3 3 3	41	4 4	200	1 4 4	3.5	44	50	3 5	20	1.1	1 1	4	1.4	20	2		3	1	F	33	3	5	30	3	I Č	
A SZUALREN EQUIPMENT	SUNTED BY MENTALDAL	5 3 3 3	41	4 4	200	1 4 4	3.5	44	50	3 5	20	1.1	1 1	4	1.4	20	2		3	1	F	33	3	5	30	3	I Č	
SAUALRIN EQUIPMENT	והאו	12.2 3990-00-020-909 400 F. 13.2 3990-00-020-909 400 F. 13.2 3990-00-020-909 4631 F. 13.2 3990-00-020-9099 4631 F.	44 44 44 44 44 44 44 44 44 44 44 44 44	9606-019-00-0660	3+ 3+5+-019-00-05+5	34 50 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	のは、 の本は大しのいはしのでしていた。 の本は大しのいはしのでしていた大い	34-0-00-620-4846 40	3990-00-620-9896 46	は、	34 3484-078-00-0446 34 3434-078-00-0446	は、 はからかしのいがしのつしつかから はないのからいのいでしています。	はず なかのかしつ はしつつしのかから	04 05 10 10 10 10 10 10 10 10 10 10 10 10 10	カナ カイントー・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	1440-100-100-100 100 110 110 110 110 110 11	41.00-00-303-3064 AR	41.0-00-3-3004	サード でした でした でんしゃ マルナー マーク・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス・ス	4120-00-00-00-00-00-00-00-00-00-00-00-00-0	131 J-00-427-00-1144	#210-00-01-00-01-00-01-01-01-01-01-01-01-0	1010-06-547-0-104	1410-00-04-1	10-00-04-00-01-4	1-18-145-00-0164	4520-00-854-5426 HE	

TYFE (MINOK)**	56. CUBE LEN WIH	198 102 60 638 201 64 1034 192 97	20000000000000000000000000000000000000	0.000 mm (0.000	22.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00		
FILTIER SURTED BY ANDITHADDRIDGE SEDAURDN TY	1.6 1910-00-895-9574 HYD FALL UNI 2.6 1910-00-895-9574 HYD FALL UNI 2.6 4910-00-895-9574 HYD FALL UNI 5.6 1910-00-997-9554 HYD FALL UNI 5.6 1910-00-997-9554 HYD FALL UNI	144 44 40 10 10 14 14 14 14 14 14 14 14 14 14 14 14 14	031 4920-00-000-0994 110-2222-18 032 4920-00-090-0994 110-22222-18 032 4920-00-090-9944 110-22222-18 034 4920-00-090-9944 110-22222-18 034 4920-01-02944 110-22222-18 034 4920-01-029944 110-22222-18 034 4920-01-029944 110-22222-18 034 4920-01-029949 01-02984 00-00-00-00-00-00-00-00-00-00-00-00-00-	14 4 4 7 3 1	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		CANCELL LITTER CONTROL LITTER CONTRO

REPORT DOCUMENTATION F	READ INSTRUCTIONS BEFORE COMPLETING FORM						
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER					
MDC J3213	of a lift						
4. TITLE (end Subtitle)		S. TYPE OF REPORT & PERIOD COVERED					
KC-10A CARGO SYSTEM MOCK-UP TEST	KC-10A CARGO SYSTEM MOCK-UP TEST						
		6. PERFORMING ORG. REPORT NUMBER					
7. AUTHOR(s)		8. CONTRACT OR GRANT NUMBER(S)					
Donald P. Danielsen		F33700-78-C-0001 New					
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS					
Douglas Aircraft Company 3855 Lakewood Blvd.							
Long Beach, California 90346	·	12. REPORT DATE					
Mechanical Engineering Section		22 August 1979					
Douglas Aircraft Company		13. NUMBER OF PAGES					
Long Beach, California 90846		77					
		15. SECURITY CLASS. (of this report)					
USAF KC-10 Joint Program Office, A Wright-Patterson AFB, Ohio, 45433	AFLC,	Unclassified					
Wright-ratterson Alb, onto, 45455		154. DECLASSIFICATION DOWNGRADING SCHEDULE					
16. DISTRIBUTION STATEMENT (of this Report)							
Unlimited							
17. DISTRIBUTION STATEMENT (of the abstract entered in	n Block 20, if different fro	m Report)					
18. SUPPLEMENTARY NOTES							
19. KEY WORDS (Continue on reverse side if necessary and	didentify by block number)						
Powered Rollers; Rotating Cargo Pa	allets; Cargo Sy	stems, Aircraft					
A test was conducted on the KC-10, the performance of the current de	A Cargo Handling	System Mock-Up to evaluate					
The test consisted of running a to							
weights loaded on the pallets. Of HCU-6/E pallets and the remaining train). These cycles simulate over	f these load/unl 111 were couple	oad cycles, 135 were single d HCU-6/E pallets (2 in					
operations.	2. 2 724.5 0. 110	(over)					

and the sale take

Unclassified
SECURITY CLASSIFICATION OF THIS PAGE/When Data Entered)

Block 20 (Continued)

The powered roller system functioned very well for the entire spectrum of loads. Single and coupled pallets were loaded laterally or rotated in the doorway easily. This test demonstrated that the system meets or exceeds its design requirements.